

0h05f2.dmi

00027
00028
00029
00030

PTMEAS/CART,-82.888,86.661,-36.216,0.000000,0.000000,1.000000
ENDMES
GOTO/-99.069,84.920,-30.000
F(PNT4)=FEAT/POINT,CART,-98.488,83.225,-40.683,-0.290663,0.847442,0.444249
MEAS/POINT,F(PNT4),1

カウンター
PNT4
補正モード: NOMINAL
1